

roadsafetyinitiatives

M65 TERMINUS ROUNDABOUT

Addendum Stage 1 Road Safety Audit Client: Maple Grove Developments

10/07/2023

Quality Management

Issue Record

ISSUE	REVISION	DESCRIPTION	DATE	PREPARED BY	CHECKED
1	-	Draft	10 July 2023	M Morley	M Hedley
Document number - RSI-MM-0723-002 M65 Issue 1.0					

- ⊠ info@roadsafetyinitiatives.co.uk www.roadsafetyinitiatives.co.uk
- @RSInitiatives
 roadsafetyinitiatives
- G+ +roadsafetyinitiatives



M65 Terminus Roundabout

Addendum Stage 1 Road Safety Audit

10/07/2023

Overseeing Organisation

National Highways

Client

Maple Grove Development

Design Organisation

WSP

Road Safety Audit Team Organisation

Road Safety Initiatives LLP

www.roadsafetyinitiatives.co.uk

Registered Address

Road Safety Initiatives LLP OC380991 c/o One Two One Accounts Limited 44 Astley Road Seaton Delaval Northumberland NE25 0DG

Enquiries regarding this audit should be made to

M Morley

Partner Road Safety Initiatives LLP

Tel: +44 (0)7758 408396 mailto: martin@roadsafetyinitiatives.co.uk



www.roadsatetyinitiatives.co @RSInitiatives

noadsafetyinitiatives

G+ +roadsafetyinitiatives



Table of Contents

1	Introduction5
2	Items Raised at the previous Road Safety Audit7
3 Audi 3	Items Raised at this Addendum Stage 1 Road Safety it
4	Audit Team Statement9
Арр	endices, Figures and Tables10
APP	ENDIX A – Scheme Documents Issued for Road Safety Audit

APPENDIX B – Location Plan



- @RSInitiatives
 roadsafetyinitiatives

G+ +roadsafetyinitiatives



1 Introduction

- 1.1.1 This report results from an Addendum Stage 1 Road Safety Audit carried out on a design change to the proposed amendments to the M65 Terminus Roundabout near Lostock Hall. The design change is an additional lane (3rd lane) on each of the two approaches to the roundabout from the east.
- 1.1.2 This Addendum Stage 1 Road Safety Audit is at the request of Hannah Barrett, WSP (Design Organisation) on behalf of Warren Hilton, National Highways (Overseeing Organisation).
- 1.1.3 The terms of reference of the Road Safety Audit are as described in DMRB GG 119. The Road Safety Audit Team has examined and reported only on the road safety implications in the scheme as presented and has not examined or verified the compliance of the designs to any other criteria.
- 1.1.4 This Addendum Stage 1 Road Safety Audit is only on the design change and therefore this report should be read in conjunction with the previous Stage 1 Road Safety Audit, issued on 5th April 2023.
- 1.1.5 The Road Safety Audit Team membership, approved by Warren Hilton, National Highways (Overseeing Organisation), consisted of:

Team Leader	Martin Morley, BSc (Hons), MCIHT, MSoRSA		
	Certificate of Competency in Road Safety Audit gained in Feb 2013		
	Partner, Road Safety Initiatives LLP		
Team Members	Mark Hedley, IEng, MCIHT, MSoRSA, FIHE, RegRSA(IHE)		
	Certificate of Competency in Road Safety Audit gained in Nov 2013		
	Partner, Road Safety Initiatives LLP		

- 1.1.6 The Addendum Stage 1 Road Safety Audit was undertaken in accordance with the Road Safety Audit Brief provided by Hannah Barrett, WSP (Design Organisation) on behalf of Warren Hilton, National Highways (Overseeing Organisation). The Road Safety Audit comprised an examination of the documents provided and listed in **Appendix A**.
- 1.1.7 The information provided for the Road Safety Audit did not include any traffic signal pole, signal head and controller locations. Similarly, no information on the intended traffic signal phasing and staging (or junction modelling output) was made available for road safety audit. The Road Safety Audit Team was therefore unable to provide detailed comments on these aspects of the design.
- 1.1.8 The Road Safety Audit Team had a meeting and visited the site (and another 'Lancashire Central' site) together on Tuesday 28th February 2023 between 10:00 and 11:30 hours. It was generally cloudy and the road surfaces were damp at the time of the site visit. Traffic flows were light and no pedestrians or cyclists were observed.
- 1.1.9 All Road Safety problems are referenced to the design drawings and the locations have been indicated on the plans supplied with the Road Safety Audit Brief in **Appendix B**.

⊠ info@roadsafetyinitiatives.co.uk

🛞 www.roadsafetyinitiatives.co.uk

@RSInitiatives

roadsafetyinitiatives
 + roadsafetyinitiatives

roadsafetyinitiatives

- 1.1.10 This Addendum Road Safety Audit will review the road safety aspects of the design change to proposed amendments at M65 Terminus Roundabout. The Design Team described the design change as "an additional lane (3rd lane) on each of the two approaches from the east, for a length of circa 100m. This third lane then feeds into the three lanes circulatory on the roundabout. Road markings on the circulatory area have also been amended to accommodate this."
- 1.1.11 The objective of the scheme is to provide safe and suitable access to the proposed 'Lancashire Central' mixed-use development.
- 1.1.12 The Road Safety Audit Team was not informed of any Departures from Standard or Strategic Decisions.



- @RSInitiatives
- in roadsafetyinitiatives G+ +roadsafetyinitiatives



Items Raised at the previous Road Safety Audit 2

2.1.1 The road safety implications of the proposed improvements at the M65 Terminus Roundabout were the subject of a Stage 1 Road Safety Audit issued in April 2023 by Road Safety Initiatives LLP. This Addendum report should be read in conjunction with the previous Stage 1 Road Safety Audit.



- @RSInitiatives
- in roadsafetyinitiatives

G+ +roadsafetyinitiatives

roadsafetyinitiatives

3 Items Raised at this Addendum Stage 1 Road Safety Audit

3.1 TRAFFIC SIGNS, CARRIAGEWAY MARKINGS AND LIGHTING

PROBLEM 3.1.1				
Location	M65 westbound carriageways.			
Summary	Possible late lane changes and swipe collisions.			
This potent	I to use 'ahead and left' arrows with worded destination markings 'A582' and 'BUS PK'. ially confusing mixing of destination arrows, leading to different exits from the t, may lead to driver hesitation, possible late lane changes and swipe collisions.			
RECOMME	NDATION			
It is recom	nended that lane arrows are omitted from the M65 westbound carriageways.			

**** END OF IDENTIFIED PROBLEMS AND RECOMMENDATIONS MADE AT THIS ADDENDUM STAGE 1 ROAD SAFETY AUDIT ****





in roadsafetyinitiatives G+ +roadsafetyinitiatives



Audit Team Statement 4

We certify that this Addendum Road Safety Audit has been carried out in accordance with GG 119.

ROAD SAFETY AUDIT TEAM LEADER			
Name:	Martin Morley		
Signed:	MatinMarley		
Position:	Partner		
Organisation:	Road Safety Initiatives LLP		
Date:	10 July 2023		
ROAD SAFETY AUDIT TEAM MEMBERS			
Name: Mark Hedley			
Signed:	Mak 5 Hub		
Position: Partner			
Organisation:	Road Safety Initiatives LLP		
Date:	10 July 2023		

- ⊠ info@roadsafetyinitiatives.co.uk www.roadsafetyinitiatives.co.uk
- @RSInitiatives
 roadsafetyinitiatives
- G+ +roadsafetyinitiatives



Appendices, Figures and Tables

⊠ info@roadsafetyinitiatives.co.uk

- 📀 www.roadsafetyinitiatives.co.uk
- @RSInitiatives
 roadsafetyinitiatives G+ +roadsafetyinitiatives

roadsafetyinitiatives

Appendix A: Scheme Documents Issued for Road Safety Audit

DRAWING NUMBER	REV	TITLE
84465-WSP-XX-DR-004	P03	M65 Terminus Roundabout*

*The same drawing, at a scale of 1:500, was also made available to the Road Safety Audit Team.






roadsafetyinitiatives G+ +roadsafetyinitiatives



Appendix B: Location Plan Numbers refer to problems identified in the text.





3.1.1

info@roadsafetyinitiatives.co.uk
 www.roadsafetyinitiatives.co.uk

- @RSInitiatives
- @RSInitiatives
 roadsafetyinitiatives

G+ +roadsafetyinitiatives

roadsafetyinitiatives

Road Safety Initiatives LLP c/o One Two One Accounts Limited 44 Astley Road Seaton Delaval Northumberland NE25 0DG

www.roadsafetyinitiatives.co.uk