



REVISIONS		
Date	Description	By

Legend:

- Top of Banking
- Bottom of Banking
- Manhole
- Inspection Cover
- British Telecom Cover
- Key - Channel
- Fence - Post & Wire
- Lamp Post
- Telegraph Pole
- Electric Pole
- Spot Top
- Gas Valve
- Water Level
- Invert Level
- Cover Level
- EL
- EL
- Ridge Level
- Benchmark / True Pt
- Spot Level
- 1:33.92
- Survey Control Station
- Top of Rock Face
- Falling Line
- Vertical Curve
- Edge of Metakote
- HL
- Invert Level
- Cover Level
- EL
- EL
- Ridge Level
- Benchmark / True Pt
- Spot Level
- 1:33.92
- Survey Control Station

Datum: Levels relative to Ordnance Survey by connection to OS Active Network by GPS



LINEAR SURVEYS LIMITED
 23 Knowler Way
 West Yorkshire
 WF15 9DGS
 Tel: 01274 893388
 Fax: 01274 893482
 e-mail: linear@linear.co.uk

Client
Mineral Planning Group Ltd

Job Title
Gale Moss, Chorley

Project Title
Restoration Plan

Scale
 1:1000 @ A2 JAN 2022

Drawn by
 SW

Checked by
 PR

DWG No
MPG/GM/22-04