

Please note: Borehole Numbers do not correspond to monitoring data or Report Reference 3373/AOP. Borehole numbers were updated post-drilling.

Borehole Log Number	Monitoring and Reporting Number
1	3
2	4
3	2
4	1













# BORE HOLE LOG


# HUGHES DRILLING

Client: MPC / Rosslyn Power Ltd.

Church Stretton, Shropshire, SY6 6LU.

Tel / Fax. 01694 751251

Email: office@hughesdrilling.co.uk



Site/Location: Coal Moss, Pimley.

B.H. No.(s): 4 Sheet No: 1 of 1

B.H. Co-ordinates: \_\_\_\_\_

Date Started: 8-4-21 Completed: 8-4-21 Drillers: MOS, DAN.


Rig Type: RC 40 Flush/Additives: \_\_\_\_\_

Drill Method: Hollow Stem Auger Casing Detail/Depth: \_\_\_\_\_

In-hole Equip: 125 ISA Others: \_\_\_\_\_

SAMPLE INTERVAL					DESCRIPTION OF STRATA/SAMPLE DRILLERS OBSERVATIONS Re: Rock Type, B.H. Conditions, Water Strikes etc.	INSTALLATION DETAILS		
RUN/ SAMPLE No.	FROM: 0 mts	TO:	Mts Drilled	Recovery Mts. Good / Poor etc.		TYPE: <u>PVC</u>	SIZE: <u>50MM</u>	HEADWORKS: <u>HI-VE</u>
	<u>0</u>					<u>0</u>		
		<u>0.40</u>	<u>0.40</u>		<u>T. SOIL</u>			<u>1.0</u>
								<u>PLUMB.</u>
					<u>SAND CRUMBL, SILTY</u>			
					<u>+ COBBLES + OCC BOULDER.</u>			<u>4.0</u>
		<u>7.0</u>	<u>7.00</u>					
		<u>EDH</u>						<u>SCREEN</u>
								<u>INC</u>
								<u>SOCK</u>
								<u>7.0</u>
					<u>WPT @ 10Y 5.0M</u>			





DH - PIEZO COVER.

CONCRETE

50MM  
PVC  
PLAIN  
PIPE

BENTONITE  
ENVIRONMENTAL  
SEAL

50MM PVC  
SLOTTED  
SCREEN  
1MC.  
GEOSOCK

GRAVEL PACK  
BACKFILL

END CAP.